


Assembly Drawing


Pakketo code:069-000029

Tools




Connecting Parts


A		62	G		30
B		20	H		4
C		2	J		1
D		1	K		1
E		2	L		
F		4	M		




1




2




3






4




5



6



7



8

Finish